

## 1. General

KCA fast charger adopts advanced high frequency switching power supply technology, divides the charging procedure into three stages, i.e. constant current ,constant voltage and floating charge, it can charge quickly with high efficiency. With small volume, light weight, fullautomatic control and simple operating mode, it is very suitable for minitype motors or low charging power batteries of various voltage.

## 2. Specification



Spec	Outline size(cm)
6V/10A	20×10×6
6V/15A	20×10×6
6V/20A	20×10×6
12V/5A	20×10×6
12V/10A	20×10×6
12V/20A	26×16×8
12V/40A	30×22×10
24V/6A	20×10×6
24V/10A	26×16×8

Spec	Outline size(cm)
24V/20A	30×22×10
36V/2A	20×10×6
36V/4A	20×10×6
36V/6A	26×16×8
36V/12A	30×22×10
48V/3A	20×10×6
48V/5A	27×16×8
48V/10A	30×22×10